DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015578 Address: 333 Burma Road **Date Inspected:** 11-Jul-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Wu Shi Gao **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

West of Bay 14-

This QA Inspector observed the following work in progress: Shielded Metal Arc Welding (SMAW) of OBG Segment 11CW corner assembly to side panel weld, SEG069A-001. ZPMC welders were identified as 044779 and 066258. ZPMC QC was identified as Li Ping. ZPMC CWI was identified as Wu Shi Gao. The welding appeared to be in conformance with welding procedure specification, WPS-345-SMAW-4G(4F)Repair and ZPMC weld repair report B-WR-9859.

Shielded Metal Arc Welding (SMAW) of OBG Segment 11CW drip plate welds, OBW11E-020 and 021. ZPMC welder was identified as 200113. ZPMC QC was identified as Li Ping. ZPMC CWI was identified as Wu Shi Gao. The welding appeared to be in conformance with welding procedure specification, WPS-B-P-2114-FCM-1.

Bay 16-

This QA Inspector observed the following work in progress: Submerged Arc Welding (SAW) of OBG Segment 13AW bottom panel weld, BP3074-001-004. ZPMC welder was identified as 045270. ZPMC QC was identified as Tao Wei. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2221-B-U3c-S-2.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Blast Bay 1-

Caltrans Quality Assurance (QA) Inspectors performed random visual inspection of OBG segment 10AW internal lower section base metal and weld surfaces. Areas requiring light grinding were marked for ZPMC personnel. Items which require repair were recorded for future repair.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation occurred this day.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer